HS&E INCIDENT BULLETIN

Italy

Type of incident: ignition & fire

Summary:

The episode happened during heating of a cover for the mechanical assembly of bearings on crankshaft of a vertical reciprocating compressor; such a cover has been by mistake located onto a wooden pallet inside the oven for three hours at a temperature of 180°C: an operator discovered that an external temperature monitor was indicating 300°C, thus signalling presence of internal fire. At that moment, He saw smoke escaping from the electric oven; erroneously He opened a little the door of the oven: flames almost reached Him. The operator put out the fire with two portable fire extinguishers; the wooden pallet which was inside, has been caught by fire.





Root Causes:

- No adequate metallic structure has been used for heating;
- lack of knowledge of combustion and fire fighting risk.

Actions Taken Thus Far: Next Steps

✓ Manufacturing of a metallic structure;



HS&E INCIDENT BULLETIN

Italy

Type of incident: ignition & fire







