

Type of Incident

Foot Injury

Summary:

Whilst working offsite, an employee was asked by the customer to assist the freeing off of a jammed slide valve. The air supply had been isolated from the valve before the work had been started, however, it was necessary to restore the air supply then re-isolate periodically. Shortly before the blockage was freed the employee was struck by the piston arm.

No Pictures available

Root Causes:

- Currently under investigation

Actions Taken Thus Far: Next Steps

- Currently under investigation