

Location Country: Italy

Type of incident: Projection of objects


Summary:

While He was drying– at the end of a hydraulic test– a compressor’s cylinder, a contractor’Operator was hit in the left eye by dust, notwithstanding He was dressing safety glasses.



This was the compressor’s cylinder in question

This type of glasses allow room to particles to fly



Root Causes:

- Unsuitable PPE to protect eyes;
- repetitive type of incident;
- lack of descriptive statistics related to this contractor;
- difficulty in finding an adequate type of PPE due to the «cold wall» phenomenon

Actions Taken Thus Far: Next Steps

- Ask the contractor to:
- give evidence of PPE training of personnel involved in the event;
- adopt goggles to protect eyes.

