

Type of Incident

*Finger Injury*

Summary:

Whilst trying to move a fan blade from its mould case, the blade slipped from its lifting sling and dropped injuring an employees finger.

No picture available

Root Causes:

- Fan was lifted using a single sling approach. This approach is unsafe and the fan can easily slip and drop

Actions Taken Thus Far: Next Steps

- Review risk assessment / Procedure for task and amend accordingly
- Review available options in the safe transportation of fan blades.
- Communicate and retrain employees involved in this task. Emphasise the importance of using the correct equipment and adopting safe practices whilst lifting